Parts Change Information

Subject: Modification of Damper; FB **Issue No.: 19510**

New Part #: See Text Below **New Description:** **Damper K; FB** **Old Part #: See Text Below** **Old Description:** **Damper; FB**	**Reason For Change** **[ ] Cost Effective** **[ ] Eliminate Claims** **[X] Easier Operation** **[ ] Other**	**Manuf. Cut-in Serial #** **N/A**	**Applies to:** **RA5900**
[ ] New	**[x] Modified**	**[ ] Obsoleted**	**[ ] Other**

SUMMARY:

The diameter of the Damper; FB has been increased.

The Support Shaft Lock has been replaced by the Support Shaft Lock II.

NEW PART NUMBERS:

1. 610-00010-005 Damper K; FB
2. 018-16262-000 Support Shaft Lock II

OLD PART NUMBERS:

1. 610-00002-207 Damper; FB
2. 018-16214-102 Support Shaft Lock



NOTE:

When the original Damper units are replaced with the Damper K; FB units, the original Support Shaft Lock must be replaced by the Support Shaft Lock II.